IMPORTANT SAFETY NOTICE

ONE WORLD TECHNOLOGIES, INC. RECALLS RYOBI MODEL P113 DUAL CHEMISTRY CHARGER



The charger can malfunction resulting in fire and burn hazards to consumers.

Sold individually and as part of a kit between September 2007 and December 2009

Only P113 chargers with manufacturing date codes between 0731-0852 <u>without</u> a nine digit part number are affected.

Consumers should *immediately* discontinue use of their charger and contact One World Technologies, Inc. Customer Service at:

1-800-597-9624

(8 a.m. to 5 p.m. ET)

for a free replacement.

Consumers can also visit www.ryobitools.com